

Table of Contents

List of Figures.....	xii
List of Tables.....	ix
Acronyms.....	xi
Acknowledgements.....	xi
1 Introduction.....	1
2 The Coastal Zone and Coastal Vulnerability	5
2.1 Threats to the coastal zone	5
2.2 Climate change, storminess and sea-level rise.....	7
2.3 Coastal management options	11
2.4 Coastal vulnerability	13
2.5 Assessing coastal vulnerability: the Coastal Vulnerability Index (CVI)	15
2.6 CVI: case study	17
3 Context and Study Area.....	20
3.1 Iceland's coastal environment.....	19
3.2 Study area.....	23
4 Methodology	29
4.1 Physical parameters	30
4.1.1 Beach width	30
4.1.2. Distance of vegetation behind back beach	31

4.1.3. Coastal slope	32
4.1.4. Percentage rocky outcrop.....	34
4.1.5 Distance from 20m isobath	35
4.1.6 Avalanche frequency	35
4.1.7 Estuary presence	36
4.2 Calculation of CVI.....	37
4.3 Socio-economic assessment.....	39
4.4 Coastal defence assessment	40
5 Physical parameter measurements.....	41
5.1 Beach width	41
5.2 Coastal slope	46
5.3 Distance from 20m isobath	49
5.4 Distance of vegetation behind back beach.....	54
5.5 Percentage rocky outcrop.....	59
5.6 Avalanche frequency	61
5.7 Estuary presence	63
6 Coastal Vulnerability Assessment	65
6.1 Coastal Vulnerability Index – Calculation.....	65
6.2 CVI analysis.....	71
6.2.1 ‘Very High’ vulnerability	71
6.2.2 Coastal sections scoring 22	73
6.2.3 Cluster of high vulnerability	75
6.3 Socio-economic assessment.....	80
6.3.1 ‘Very high’ vulnerability	81
6.3.2 Coastal sections scoring ’21-22’	84

6.4 Coastal defence assessment	85
7 Conclusion	89
References.....	93
Appendix A	101
Appendix B	103

List of Figures

Figure 2.1 Synergetic multi-stressors found in the coastal zone	5
Figure 2.2 Global mean temperature (°C) 1890-2005	7
Figure 2.3 Annual averages of the global mean sea level (Units are in mm relative to the average for 1961 to 1990)	9
Figure 2.4 Coastal vulnerability framework	14
Figure 2.5 CVI formula devised by Gornitz (1989)	15
Figure 2.6 Variable classifications for sub-indices in McLaughlin and Cooper's CVI for Northern Ireland.....	17
Figure 2.7 Palmer et al.'s study CVI formula.....	18
Figure 3.1 Map of Iceland.....	20
Figure 3.2 Photos of seawall defences constructed in Iceland.....	22
Figure 3.3 Study area: from Kambnes (the northern-most point of Álftafjörður) and Hafnarhýrna (the western-most point of Dýrafjörður).....	24
Figure 3.4 Map of Holtstangi	25
Figure 3.5 Map showing Flateyri and Ísafjörður.	26
Figure 3.6 Image of outer Ísafjörður	27
Figure 3.7 Road located near Hnífsdalur	28
Figure 4.1 Example of beach width measurement using an orthophotograph.....	31
Figure 4.2 Example of distance of vegetation behind back beach measurement using an orthophotograph.....	32

Figure 4.3 Example of coastal slope being measurement using Google Earth.....	34
Figure 4.4 Examples of bathymetry maps used: Chart no46	35
Figure 4.5 Example of estuary presence in Önundarfjörður	37
Figure 4.6 CVI equation	38
Figure 5.1 Beach width measurements graph	42
Figure 5.2 Beach width measurement for coastal section 142 and upper reaches of Önundarfjörður	43
Figure 5.3 Beach width measurement for coastal section 10.....	44
Figure 5.4 Ísafjörður harbour and Ísafjörður airport runway.....	45
Figure 5.5 Beach width measurement for coastal section 109.....	45
Figure 5.6 Coastal slope measurementsgraph.....	47
Figure 5.7 Coastal slope measurement for coastal section 80	48
Figure 5.8 Coastal slope measurement for coastal section 143	49
Figure 5.9 Distance to 20m-isobaths measurements graph	51
Figure 5.10 Extract from Icelandic Bathymetry map Chart no46	52
Figure 5.11 Bathymetry data for Dýrafjörður.....	52
Figure 5.12 The upper reaches of Súgandafjörður (left) and Önundarfjörður (right), where the shallowest waters of the study area were located.	53
Figure 5.13 Distance of vegetation behind back beach graph	55
Figure 5.14 Distance of vegetation behind back beach measurement for coastal section 31 ...	56
Figure 5.15 Examples of the highest measurements for vegetation behind the back beach.....	57
Figure 5.16 Examples of 0m of vegetation behind the back beach recorded	58
Figure 5.17 Percentage rocky outcrop measurements graph	60
Figure 5.18 Examples of % rock outcrop	61
Figure 5.19 Examples of estuaries found in the study area	64
Figure 6.1 Distribution graph of CVI scores	66
Figure 6.2 Line graph representing CVI scores for coastal section: 1-240	67

Figure 6.3 Maps visually representing CVI scores found across study area. (a) Total study area, (b) Álftafjörður, (c) Skutulsfjörður, (d) Óshlíð, Bolungarvík, Skálavík and Súgandafjörður, (e) Önundarfjörður, (f) Dýrafjörður	68
Figure 6.4 Orthophotograph images of ‘very high’ vulnerability coastal sections. From top left; coastal sections 61, 190 and 227	72
Figure 6.5 Orthophotograph images of coastal sections scoring ‘22’. From top left; 124, 149, 192, 219 and 232.....	74
Figure 6.6 Orthophotographimage of coastal sections 10-13	76
Figure 6.7 Orthophotographs image of coastal sections 26-29.....	77
Figure 6.8 Orthophotographimage of coastal sections 60-63	79
Figure 6.9 Orthophotograph image of coastal sections 88-91 (located on the northern coastline of the fjord)	80
Figure 6.10 Orthophotograph images of socio-economic features present in coastal section 61. (a) lighthouse, (b) minor road, (c) Djúpvegur.....	82
Figure 6.11 Orthophotograph images of socio-economic features present in coastal section 190. (a) Vestfjarðarvegur, (b) boat launch site	83
Figure 6.12 Orthophotograph images of the Þingeyri airstrip, ~550m inland from the shoreline at the western edge of coastal section 227.	84

List of Tables

Table 2.1 Main climate drivers for coastal systems, their trends due to climate change, and their main physical and ecosystem effects	8
Table 2.2 CVI parameter ranking for Palmer et al.’s study	18
Table 2.3 Key socio-economic features found in the KwaZulu-Natal coastal environment	19
Table 4.1 Criteria for physical parameter rankings.....	37
Table 4.2 Categories and features of socio-economic features using Ketchum’s (1972) ‘main spheres of activity in the coastal zone’	39
Table 5.1 Beach width measurements	41
Table 5.2 Coastal slope measurements	46
Table 5.3 Distance from 20m-isobath measurements.....	49

Table 5.4 Distance of vegetation behind back beach measurements	54
Table 5.5 Percentage rocky outcrop measurements.....	59
Table 5.6 Records of avalanches impact major roads (1996-2011).....	61
Table 5.7 Description of coastal sections at risk of avalanches.....	63
Table 6.1 CVI scores for coastal sections 1-240.....	65
Table 6.2 Physical parameter measurements and CVI rankings for coastal sections scoring ‘very high’ vulnerability	71
Table 6.3 Physical parameter measurements for coastal sections scoring 22.....	73
Table 6.4 Physical parameter measurements and vulnerability ranking: coastal sections 10-13	75
Table 6.5 Physical parameter measurements and vulnerability ranking: coastal sections 26-29	77
Table 6.6 Physical parameter measurements and vulnerability ranking: coastal sections 60-63.....	78
Table 6.7 Physical parameter measurements and vulnerability ranking: coastal section 88-91.....	79
Table 6.8 Potential socio-economic features to located within cells of coastal sections.....	81
Table 6.9 Socio-economic features located in ‘very high’ vulnerability coastal sections.....	81
Table 6.10 Socio-economic features located in coastal sections scoring 21-22.....	84
Table 6.11 Coastal defence assessment for coastal sections scoring 22-23	86
Table 6.12 Coastal defence assessment for clusters of high vulnerability coastal sections	87